

1/16

PRESSURIZING DISK

Figure 1






Figure 2



3/16

Figure 3



4/16

Figure 4




Figure 5




Figure 6





Figure 7



8 / 16

Figure 8




Figure 9

9 / 1 6




Figure 10

10/16





Figure 11

11/16

a) SINTERING OF THICK PORTION



b) SINTERING OF THIN PORTION





Figure 12

12/16

- a) When the Terminal Assembly is thick,
the difference between T1 and T2 is large.



- b) When the Terminal Assembly is thin,
the difference between T1' and T2' is small.






Figure 13



14/16

Figure 14



15/16

Figure 15




Figure 16

